

**Table 3 Quality assurance staff responses to question about levels of self-inspection for good manufacturing practice (GMP)**

<b>Aspects of GMP for self-inspection</b>	<b>No.</b>	<b>% (<i>n</i> = 23)</b>
Personnel working in the facility	19	82.6
Maintenance of the factory	14	60.9
Manufacturing and testing	17	73.9
Quality control procedure	22	95.7
Documentation preparation	19	82.6
Recall procedures	15	65.2
Follow-up to previous self-inspections	14	60.9
Validation and monitoring procedures	15	65.2
Control of printed components	16	69.6